



YOUR INSPECTION REPORT

Inspection, Education, Knowledge.

PREPARED BY:
ADAM HANNAN



FOR THE PROPERTY AT:

387 Durie Street
Toronto, ON M6S 3G5

PREPARED FOR:
LESLEY SRIVASTAVA
NAVIN SRIVASTAVA

INSPECTION DATE:
Friday, May 24, 2019

TIP

THE
INSPECTION
PROFESSIONALS

THE INSPECTION PROFESSIONALS, INC.
3120 Rutherford Rd.
Concord, ON L4K 0B2

416-725-5568
HST# 89249 4501 RT0001

www.inspectionpros.ca
adam@inspectionpros.ca

TIP

THE
INSPECTION
PROFESSIONALS

May 27, 2019

Dear Lesley Srivastava and Navin Srivastava,

RE: Report No. 2460, v.2
387 Durie Street
Toronto, ON
M6S 3G5

Thank you for choosing The Inspection Professionals to perform your Home Inspection.

The Inspection Professionals (TIP) is a Full-Time Professional, Certified multi-inspector company founded by Adam Hannan. Since 2006, Adam has performed thousands of residential and commercial inspections and has become a respected expert in his field. Adam has a passion for education and has been an inspection instructor teaching at Community Colleges and Universities since 2009.

Adam is a member of the Ontario Association of Home Inspectors and International Association of Certified Home Inspectors.

"We inspect every home as if we were buying it for ourselves. We care about our clients and we strive to exceed expectations. We offer a professional unbiased opinion of the current performance of the home regardless of who we are working for."

-Adam

BUYERS -

An Onsite Review is an essential component to a complete home inspection. In order to more thoroughly familiarize yourself with the property and our findings, please book an Onsite Review at your convenience by calling (416) 725-5568. Once we have completed the Onsite Review, we will transfer the inspection report to the buyer. The fee for this service is only \$249. (A minimum savings of \$175)

Sincerely,

ADAM HANNAN
on behalf of
THE INSPECTION PROFESSIONALS, INC.

THE INSPECTION PROFESSIONALS,
INC.
3120 Rutherford Rd.
Concord, ON L4K 0B2
416-725-5568
HST# 89249 4501 RT0001
www.inspectionpros.ca
adam@inspectionpros.ca

SUMMARY

387 Durie Street, Toronto, ON May 24, 2019

Report No. 2460, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

This Summary outlines some of the potentially short-term significant issues from a cost standpoint. This section is provided as a COURTESY ONLY and cannot be considered a substitute for reading the entire report. Please read the complete document.

It is not possible for a home inspector to predict the future. It would be advisable to annually budget between 0.5% to 1% of the value of the home for unforeseen repairs and maintenance. This would hold true for any house that you were considering.

Things will wear out, break down, and fail without warning. This is a fact of home ownership.

NOTE: ALL ELECTRICAL ISSUES ARE CONSIDERED PRIORITY ITEMS

NOTE: FOR BALLPARK COSTS THE TERM 'MINOR' REFERS TO COSTS UNDER \$500

NOTE: FOR DIRECTIONAL PURPOSES USED THROUGHOUT THE REPORT, THE "FRONT" OF THE HOUSE IS REFERENCED AS FACING THE FRONT DOOR FROM THE EXTERIOR.

During a home inspection we inspect all visible systems and components. There are literally hundreds of potential minor issues found in every home, new and old. The focus of this inspection was not to list all the minor deficiencies. But rather, the focus of this inspection was to identify MAJOR issues with MAJOR systems and components. To simplify and give you a better understanding of what is considered a major issue, the inspection can generally be categorized as follows.

- 1)OBSERVABLE STRUCTURAL DEFECTS
- 2)OBSERVABLE WATER LEAKAGE/DAMAGE Roof, Plumbing, and basement moisture intrusion.
- 3)OBSERVABLE ELECTRICAL DEFECTS
- 4)LIFESPAN SYSTEMS- Roof Covering, Heating System, Cooling System, Windows

For Ballpark costs of various home components, please click here:

<http://www.inspectionlibrary.com/costs.htm>

Cooling & Heat Pump

AIR CONDITIONING \ Life expectancy

Condition: • [Old](#)

Typical life expectancy for a/c units are 10-15 years. The current unit is 30 years old and is beyond its life expectancy. The outdoor unit was covered. To avoid damage, a/c units are not tested until they have been started up for the season. Plan for replacement

Implication(s): Equipment failure | Reduced comfort

Location: Front Exterior

Task: Replace

Time: When necessary / Unpredictable

Cost: \$3,000 - and up

SUMMARY

387 Durie Street, Toronto, ON May 24, 2019

Report No. 2460, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

Interior

POTENTIALLY HAZARDOUS MATERIALS \ General

Condition: • Possible asbestos containing materials

During the era when this house was built up until the 1960s, it was very common to wrap registers in asbestos type insulation to protect the floors from overheating. Determining the material type is outside the scope of this inspection. Health Canada recommends that any asbestos material found should stay in place undisturbed. If you plan to remodel or if this is a concern, consult with a specialist for lab testing to confirm if asbestos is present.

Implication(s): Health hazard

Location: Heating registers

Task: Evaluate before disturbing or if desired

Cost: Not determined - outside our scope of work

This concludes the Summary section.

The remainder of the report describes each of the home's systems and also details any recommendations we have for improvements. Limitations that restricted our inspection are included as well.

The suggested time frames for completing recommendations are based on the limited information available during a pre-purchase home inspection. These may have to be adjusted based on the findings of specialists.

<http://www.inspectionlibrary.com/wtgw.htm>

ROOFING

387 Durie Street, Toronto, ON May 24, 2019

Report No. 2460, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

Descriptions

Sloped roofing material: • [Asphalt shingles](#)

Flat roofing material: • [Modified bitumen membrane](#)

Approximate age:

• New

Seller noted Flat Roof was replaced this year April 2019

• 11 years

Seller noted Sloped Roof Covering was replaced in 2008

Observations and Recommendations

RECOMMENDATIONS \ Overview

Condition: • Seller reported that flat roof covering was recently fully replace in April 2019. We did not observe flat roof

Task: Request Documentation for records

Condition: • Most roofs are susceptible to ice dams under the right weather conditions. This is where ice forms at the lower edge of a sloped roof, causing melting water from above to back up under the shingles. We cannot predict which roofs will suffer the most damage under adverse weather

SLOPED ROOFING \ Asphalt shingles

Condition: • [Vulnerable areas](#)

Skylights are vulnerable areas. Monitor regularly especially after heavy rainfalls.

Location: Skylight

Task: Monitor

Time: ongoing

ROOFING

387 Durie Street, Toronto, ON May 24, 2019

Report No. 2460, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR


LINKS

PHOTOS

MORE INFO

REFERENCE

Vulnerable areas



Inspection Methods and Limitations

Inspection performed: • Through Window - Limited View

Inspection performed: • With binoculars from the ground

EXTERIOR

387 Durie Street, Toronto, ON May 24, 2019

Report No. 2460, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

Descriptions

Gutter & downspout material: • [Aluminum](#)

Gutter & downspout discharge: • [Above grade](#)

Lot slope: • [Away from building](#) • [Flat](#)

Wall surfaces - masonry: • [Brick](#)

Observations and Recommendations

ROOF DRAINAGE \ Gutters

Condition: • Aging - Wear and tear noted. Fasteners loose in some areas

Location: Exterior

Task: Improve

Time: Regular maintenance



1. Aging - Wear and tear noted. Fasteners...

ROOF DRAINAGE \ Downspouts

Condition: • [Damage](#)

Implication(s): Chance of water damage to contents, finishes and/or structure

Location: Front Exterior

Task: Repair / Replace

Time: Less than 1 year

Cost: Minor

EXTERIOR

387 Durie Street, Toronto, ON May 24, 2019

Report No. 2460, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

Downspouts - common leakage areas

leaking
elbows
and seams

split along
back seam

clogged

staining or
efflorescence



2. Damage

Condition: • [Not well secured](#)

Implication(s): Leakage

Location: Exterior Wall

Task: Improve

Time: Regular maintenance

Cost: Regular maintenance item

EXTERIOR

387 Durie Street, Toronto, ON May 24, 2019

Report No. 2460, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE



3. Not well secured

WALLS \ Masonry (brick, stone) and concrete

Condition: • Most masonry walls have small cracks due to shrinkage or minor settlement. These will not be individually noted in the report, unless leakage, building movement or similar problems are noted

DOORS \ Exterior trim

Condition: • [Damaged, cracked or loose](#)

Location: Front Exterior

Task: Repair / Replace

Time: Less than 1 year

Cost: Regular maintenance item



4. Damaged, cracked or loose

PORCHES, DECKS, STAIRS, PATIOS AND BALCONIES \ Columns / Posts

Condition: • [Spalling](#)

Implication(s): Weakened structure | Chance of movement

Location: Front Exterior

Task: Repair

EXTERIOR

387 Durie Street, Toronto, ON May 24, 2019

Report No. 2460, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

Time: Less than 2 years

Cost: Regular maintenance item



5. Spalling

PORCHES, DECKS, STAIRS, PATIOS AND BALCONIES \ Handrails and guards

Condition: • [Loose](#)

Implication(s): Fall hazard

Location: Front Exterior Porch

Task: Repair / Replace

Time: Less than 1 year

Cost: Depends on approach



6. Loose

Condition: • [Too low](#)

Below modern standards

Implication(s): Fall hazard

Location: Front Exterior Porch

Task: Upgrade

Time: Discretionary

EXTERIOR

387 Durie Street, Toronto, ON May 24, 2019

Report No. 2460, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR


LINKS

PHOTOS

MORE INFO

REFERENCE

Handrails or guards too low



LANDSCAPING \ Lot grading

Condition: • During rainfall, walk the exterior to view if any water is draining towards the home. Improve these areas as needed

GENERAL RECOMMENDATION FOR ALL HOMES

Inspection Methods and Limitations

Upper floors inspected from: • Ground level

Descriptions

Configuration: • [Basement](#)

Foundation material:

• [Brick](#)

• Not visible

Not visible in most areas

Floor construction: • [Joists](#)

Exterior wall construction: • [Masonry](#)

Observations and Recommendations

FOUNDATIONS \ General

Condition: • [Parging damaged or missing](#)

Implication(s): Chance of damage to structure | Shortened life expectancy of material

Location: Exterior Wall

Task: Repair

Time: Regular maintenance

Cost: Regular maintenance item



7. Parging damaged or missing

WALLS \ Arches

Condition: • [Masonry units moving](#)

It is common for masonry arches of this age to require masonry or mortar maintenance

Location: Front Exterior Wall

Task: Repair

Time: Less than 2 years

Cost: Regular maintenance item

STRUCTURE

387 Durie Street, Toronto, ON May 24, 2019

Report No. 2460, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE



8.

Condition: • [Cracked](#)

Very common to find cracks and settlement at arches above windows or door. The masonry below has been repair and a steel support has been added above the door. Patch any gaps at the arch to prevent further damage and/or movement

Implication(s): Weakened structure | Chance of structural movement


Location: Rear Exterior Wall

Task: Patch


Time: Less than 2 years

Cost: Regular maintenance item

Lintel related wall cracks




crack pattern commonly associated with sagging lintels due to undersizing or deterioration



horizontal crack is often caused by rusting steel lintels expanding



cracking caused by deterioration of wood lintel



cracking due to insufficient material beside arch to resist lateral thrust

STRUCTURE

387 Durie Street, Toronto, ON May 24, 2019

Report No. 2460, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE



9.

Inspection Methods and Limitations

Inspection limited/prevented by: • Ceiling, wall and floor coverings • Carpet/furnishings • Storage • New finishes/paint

Attic/roof space: • Inspected from access hatch

Percent of foundation not visible: • 95 %

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

Descriptions


General: • ALL ELECTRICAL CONDITIONS ARE CONSIDERED PRIORITY ITEMS

Service entrance cable and location: • [Overhead - cable type not determined](#)

Service size: • [100 Amps \(240 Volts\)](#)

Main disconnect/service box type and location:

• [Breakers - basement](#)



10. Breakers - basement

Distribution panel type and location: • [Breakers - basement](#)

Distribution panel rating: • [125 Amps](#)

Distribution wire material and type: • [Copper - non-metallic sheathed](#) • [Copper - metallic sheathed](#)

Type and number of outlets (receptacles): • [Grounded - upgraded](#)

Circuit interrupters: Ground Fault (GFCI) & Arc Fault (AFCI): • [GFCI - bathroom and exterior](#)

Smoke alarms (detectors): • [Present](#)

Observations and Recommendations

DISTRIBUTION SYSTEM \ Knob-and-tube wiring

Condition: • [Replace when renovating](#)

Seller reported that all knob and tube was removed when they upgraded the wiring. We did not observe any active knob and tube during our inspection. Sometimes Knob and Tube is found during renovations. If found, replacement is recommended to satisfy insurance companies.

DISTRIBUTION SYSTEM \ Junction boxes

Condition: • [Cover loose or missing](#)

Implication(s): Electric shock | Fire hazard

Location: Basement Furnace Room

Task: Cover

Time: Immediate

Cost: Less than \$100



11. Cover loose or missing

DISTRIBUTION SYSTEM \ Outlets (receptacles)

Condition: • [Test faulty on GFCI/GFI \(Ground Fault Circuit Interrupter\)](#)

Implication(s): Electric shock

Location: Second Floor Bathroom

Task: Correct

Time: Prior to first use

Cost: Minor

DISTRIBUTION SYSTEM \ Smoke alarms (detectors)

Condition: • Smoke and carbon monoxide (CO) detectors should be provided at every floor level of every home. Smoke detectors should be close to sleeping areas, and carbon monoxide detectors should be in any room with a wood-burning stove or fireplace. These devices are not tested as part of a home inspection. Once you take possession of the home, detectors should be tested regularly, and replaced every 10 years. If unsure of the age of a smoke detector, it should be replaced. Smoke detector batteries should be replaced annually.

Inspection Methods and Limitations

System ground: • Quality of ground not determined

HEATING

387 Durie Street, Toronto, ON May 24, 2019

Report No. 2460, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

Descriptions

System type: • [Furnace](#)

Fuel/energy source: • [Gas](#)

Heat distribution: • [Ducts and registers](#)

Approximate capacity: • [90,000 BTU/hr](#)

Efficiency: • [High-efficiency](#)

Approximate age: • [10 years](#)

Typical life expectancy: • Furnace (high efficiency) 15 to 20 years

Fireplace/stove:

• [Gas fireplace](#)

Main Floor

• Decorative only

Upper Floor

Observations and Recommendations

General

• Set up annual service plan which includes coverage for parts and labour.

Location: Basement Furnace Room

Task: Service annually

Time: Ongoing

Cost: Regular maintenance item

CHIMNEY AND VENT \ Masonry chimney

Condition: • [Loose, missing or deteriorated masonry](#)

Appears to be an abandoned chimney. Rather than repair, you may consider removing the chimney altogether.

Implication(s): Material deterioration

Location: Rear Chimney (at flat roof)

Task: Remove

Time: As Required



12. Loose, missing or deteriorated masonry

CHIMNEY AND VENT \ Masonry chimney cap

Condition: • [No drip edge on cap](#)

Implication(s): Chance of water damage to contents, finishes and/or structure | Shortened life expectancy of material | Material deterioration


Location: Exterior

Task: Improve

Time: Less than 1 year

Cost: Minor

What makes a good chimney cap?



HEATING

387 Durie Street, Toronto, ON May 24, 2019

Report No. 2460, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR


LINKS

PHOTOS

MORE INFO

REFERENCE

Drip edge on cap



13. No drip edge on cap

Inspection Methods and Limitations

Safety devices: • Not tested as part of a building inspection

Heat loss calculations: • Not done as part of a building inspection

Heat exchanger: • Not visible

COOLING & HEAT PUMP

387 Durie Street, Toronto, ON May 24, 2019

Report No. 2460, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

Descriptions

Air conditioning type: • [Air cooled](#)

Cooling capacity: • [24,000 BTU/hr](#)

Compressor approximate age: • 30 years

Typical life expectancy: • 10 to 15 years

Observations and Recommendations

General

• In general, air conditioning units have a lifespan of 10-15 years but often last longer with regular servicing.

AIR CONDITIONING \ Life expectancy

Condition: • [Old](#)

Typical life expectancy for a/c units are 10-15 years. The current unit is 30 years old and is beyond its life expectancy. The outdoor unit was covered. To avoid damage, a/c units are not tested until they have been started up for the season. Plan for replacement

Implication(s): Equipment failure | Reduced comfort

Location: Front Exterior

Task: Replace

Time: When necessary / Unpredictable

Cost: \$3,000 - and up

Inspection Methods and Limitations

Inspection limited/prevented by: • To reduce risk of damaging the compressor, air conditioning systems are not tested until they have been started up for the season.

Inspection limited/prevented by: • Outdoor unit covered

Heat gain/loss calculations: • Not done as part of a building inspection

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

Descriptions

Attic/roof insulation material: • [Glass fiber](#)

Attic/roof insulation amount/value: • [R-20](#) • [R-24](#)

Attic/roof air/vapor barrier: • Spot Checked Only

Attic/roof air/vapor barrier: • [None found](#)

Attic/roof ventilation: • [Roof and soffit vents](#)

Observations and Recommendations

ATTIC/ROOF \ Insulation

Condition: • [Amount less than current standards](#)

Below current standards of R-50 (as of 2012) . Also gaps or voids in insulation observed

Implication(s): Increased heating and cooling costs

Location: Throughout Attic

Task: Upgrade

Time: Discretionary

Cost: \$1,000 - and up



14. Amount less than current standards



15. Amount less than current standards

ATTIC/ROOF \ Hatch/Door

Condition: • [Not insulated and not weatherstripped](#)

Implication(s): Chance of condensation damage to finishes and/or structure | Increased heating and cooling costs | Reduced comfort

Location: Attic

Task: Improve

Time: Less than 1 year

Cost: Minor

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS


MORE INFO

REFERENCE

Attic access hatch

the illustration shows a good attic access hatch design

hatches in many houses (especially older ones) won't meet these ideals



Inspection Methods and Limitations

Inspection prevented by no access to: • Walls, which were spot checked only

Attic inspection performed: • From access hatch

Roof ventilation system performance: • Not evaluated

Air/vapor barrier system: • Continuity not verified

Descriptions

Service piping into building: • [Copper](#)

Supply piping in building: • PEX (cross-linked Polyethylene)

Main water shut off valve at the:

- Basement



16. Basement

Water flow and pressure: • [Functional](#)

Water heater type: • [Induced draft](#)

Water heater fuel/energy source: • [Gas](#)

Water heater tank capacity: • 189 liters

Water heater approximate age: • 8 years

Water heater typical life expectancy: • 10 to 15 years

Waste and vent piping in building: • [Plastic](#)

Floor drain location:

- Near laundry area

Reported by Homeowner to be in laundry room below washer

Observations and Recommendations

WASTE PLUMBING \ Drain piping - performance

Condition: • Seller noted that clay waste lines from house to street were replaced with plastic waste lines in 2012

Condition: • Sewage backup insurance is recommended.

Implication(s): drainage and/or leakage problems

Location: Basement

Task: Provide

Time: Immediate

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

Condition: • Drain line video camera inspection recommended

RECOMMENDED FOR ALL HOMES BUILT PRIOR TO 1970. SELLER NOTED THAT CLAY WASTE LINES FROM HOUSE TO STREET WERE REPLACED WITH NEW PLASTIC WASTE LINES.

Implication(s): Drainage and/or leakage problems

Location: Basement

Task: Camera inspection

Time: Immediate

WASTE PLUMBING \ Floor drain

Condition: • Not visible

Seller noted that floor drain is below washing machine

Location: Basement

FIXTURES AND FAUCETS \ Shower stall

Condition: • Loose fixture

Location: Basement Bathroom

Task: Improve

Time: Less than 1 year

Cost: Regular maintenance item



17.

FIXTURES AND FAUCETS \ Toilet

Condition: • [Loose](#)


Implication(s): Chance of water damage to contents, finishes and/or structure | Sewage entering the building

Location: Basement Bathroom

Task: Improve

Time: Regular maintenance

Loose toilet



Inspection Methods and Limitations

Items excluded from a building inspection: • Tub and basin overflows are not tested as part of a home inspection. Leakage at the overflows is a common problem.

Items excluded from a building inspection: • Well • Water quality • Septic system • Isolating/relief valves & main shut-off valve • Concealed plumbing • Tub/sink overflows • Water treatment equipment • Pool • Spa

Descriptions

Major floor finishes: • [Carpet](#) • [Hardwood](#)

Major wall and ceiling finishes: • [Plaster/drywall](#) • [Stucco/texture/stipple](#)

Windows: • [Fixed](#) • [Sliders](#) • [Casement](#)

Glazing: • [Double](#) • [Primary plus storm](#)

Exterior doors - type/material: • Hinged • [Sliding glass](#)

Observations and Recommendations

General

• Typical minor flaws were noted on floors, walls and ceilings. These cosmetic issues reflect normal wear and tear

CEILINGS \ General

Condition: • Typical flaws

Location: Second Floor Bedroom closet

Task: For your information

Condition: • Patched

Tested with moisture meter. Dry at time of inspection

Location: Basement

Task: For Your Information



18. Patched

Condition: • Stains

Minor stain. Tested with moisture meter. Dry at time of inspection

Implication(s): Chance of water damage to contents, finishes and/or structure

Location: Second Floor Ceiling

Task: For your information



19. Stains

FLOORS \ Subflooring

Condition: • Slope or Sag Noted. Older homes tend to have saggy, sloping floors. If you choose to make repairs to level the floors, repairs can require invasive and extensive work.

Location: Various Second Floor

Task: For Your Information

Condition: • [Squeaks](#)

Typical for a home of this age

Implication(s): Noise nuisance

Location: Second Floor

Task: For Your Information

WINDOWS \ General

Condition: • We noted windows of varying ages. We typically recommend replacement only when inoperative or leaky windows are found. Replacement of functioning windows, however old, are discretionary.

Location: Various

Task: Upgrade

Time: Discretionary

Cost: \$40-\$80 sq ft. installed

WINDOWS \ Hardware

Condition: • [Loose](#)

Casement arm becomes detached from window.

Implication(s): Equipment failure

Location: Bathroom

Task: Repair

Time: Regular maintenance

INTERIOR

387 Durie Street, Toronto, ON May 24, 2019

Report No. 2460, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE



20. Loose

DOORS \ Doors and frames

Condition: • [Damage](#)

Location: Front Door near bottom

Task: Repair / Replace

Time: Discretionary

Condition: • [Racked/out-of-square](#)

Location: Second Floor Bedroom

Task: Adjust

Time: As Needed

STAIRS \ Handrails and guards

Condition: • [Missing](#)

Implication(s): Fall hazard


Location: Staircases

Task: Provide


Time: As Soon As Possible

Cost: Minor

Handrails and guards



21. Missing



22. Missing

BASEMENT \ Leakage

Condition: • ***FOR FUTURE REFERENCE*** Basement Leakage 4-step method.

Almost every basement (and crawlspace) leaks under the right conditions. Based on a one-time visit, it's impossible to know how often or severe leaks may be. While we look for evidence of past leakage during our inspection, this is often not a good indicator of current conditions. Exterior conditions such as poorly performing gutters and

SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
LINKS	PHOTOS	MORE INFO	REFERENCE						

downspouts, and ground sloping down toward the house often cause basement leakage problems. To summarize, wet basement issues can be addressed in 4 steps: 1. First, ensure gutters and downspouts carry roof run-off away from the home. (relatively low cost) 2. If problems persist, slope the ground (including walks, patios and driveways) to direct water away from the home. (Low cost if done by homeowner. Higher cost if done by contractor or if driveways, patios and expensive landscaping are disturbed.) 3. If the problem is not resolved and the foundation is poured concrete, seal any leaking cracks and form-tie holes from the inside. (A typical cost is \$300 to \$600 per crack or hole.) 4. As a last resort, dampproof the exterior of the foundation, provide a drainage membrane and add/repair perimeter drainage tile. (High cost)

BASEMENT \ Wet basements - vulnerability

Condition: • Typical of many homes with stone, brick, or block foundations, some moisture can be expected from time to time and is not unusual. Exterior grading and water management improvements are generally effective at reducing basement moisture. A dehumidifier can also be used to keep humidity levels down.

POTENTIALLY HAZARDOUS MATERIALS \ General

Condition: • Possible asbestos containing materials

During the era when this house was built up until the 1960s, it was very common to wrap registers in asbestos type insulation to protect the floors from overheating. Determining the material type is outside the scope of this inspection. Health Canada recommends that any asbestos material found should stay in place undisturbed. If you plan to remodel or if this is a concern, consult with a specialist for lab testing to confirm if asbestos is present.

Implication(s): Health hazard

Location: Heating registers

Task: Evaluate before disturbing or if desired

Cost: Not determined - outside our scope of work



23. Possible asbestos containing materials

Inspection Methods and Limitations

General: • Up until about 1985, Asbestos was used in a multitude of building materials including but not limited to: Insulation on hydronic piping, attic insulation, flooring and ceiling tiles, stucco ceilings, glue, insulation around heating ducts and registers and so on. Identification of asbestos is outside the scope of a home inspection. If you have concerns about asbestos, consult with a professional environmental company that specializes with asbestos lab testing.

Inspection limited/prevented by: • Storage/furnishings • New finishes/paint • Storage in closets and cabinets / cupboards

Not included as part of a building inspection: • Carbon monoxide alarms (detectors), security systems, central vacuum • Cosmetic issues • Appliances • Perimeter drainage tile around foundation, if any

Cosmetics: • No comment offered on cosmetic finishes

Appliances: • Appliances are not inspected as part of a building inspection • Appliances are not moved during an inspection

Percent of foundation not visible: • 95 %

Basement leakage: • Cannot predict how often or how badly basement will leak • Storage in basement limited inspection

Environmental issues are outside the scope of a home inspection : • This includes issues such as asbestos.

LINKS

387 Durie Street, Toronto, ON May 24, 2019

Report No. 2460, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

Descriptions

General: • [The Inspection Professionals Website](#)

General: • [Low concentrations of CO can go undetected and can contribute to ongoing, unidentified illnesses. At high concentrations, it can be deadly.](#)

General: • [Serious structural problems in houses are not very common, but when they occur they are never cheap to fix.](#) Some cant be fixed at all. This report wont turn you into a home inspector, but it will give you some of the common indicators.

General: • [There are so many home maintenance and repair items that are important; it can be confusing trying to establish which are the most critical.](#)

General: • [\(Life Cycles and Costs\)](#)

General: • [This report will deal with the simpler topic of home repair--basically replacing things that are worn out or fixing things that are broken.](#)

General: • [Common Building Technical Terms Explained](#)

PHOTOS

387 Durie Street, Toronto, ON May 24, 2019

Report No. 2460, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

Descriptions

General: • pictures taken during inspection

MORE INFO

387 Durie Street, Toronto, ON May 24, 2019

Report No. 2460, v.2

www.inspectionpros.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

Descriptions

GOOD ADVICE FOR ALL HOMEOWNERS: • The following items apply to all homes and explain how to prevent and correct some common problems.

Roof Leaks: • Roofs may leak at any time. Leaks often appear at roof penetrations, flashings, changes in direction or changes in material. A roof leak should be addressed promptly to avoid damage to the structure, interior finishes and furnishings. A roof leak does not necessarily mean the roof has to be replaced.

Annual Roof Maintenance: • We recommend an annual inspection and tune-up to minimize the risk of leakage and to maximize the life of your roof.

Ice Dams on Roofs: • [Most roofs are susceptible to ice dams under the right weather conditions. This is where ice forms](#) at the lower edge of a sloped roof, causing melting water from above to back up under the shingles. We cannot predict which roofs will suffer the most damage under adverse weather.

Maintaining the Exterior of Your Home: • Regular maintenance includes painting and caulking of all exterior wood.

Insulation Amounts - Current Standards: • Attic and roof space: R-40 (R-50 if electric heat)

Reduce Air Leaks: • Insulation is not effective if air (and the heat that goes with it) can escape from the home. Caulking and weather-stripping help control air leakage, improving comfort while reducing energy consumption and costs. Air leakage control improvements are inexpensive and provide a high return on investment.

Bathtub and Shower Maintenance: • Caulking and grout in bathtubs and showers should be checked every six months and improved as necessary to prevent leakage and damage behind wall surfaces.

Basement/Crawlspace Leakage: • Almost every basement (and crawlspace) leaks under the right conditions. • [Click](#) for more information.

MORE GOOD ADVICE FOR ALL HOMES: • Here is some more information that applies to all homes.

MORE GOOD INFORMATION: • The following links give you access to documents that provide additional information on a range of topics.

Life Cycles and Costs: • [Ballpark estimates based on a typical three-bedroom home.](#)

Priority Items for Home Buyers: • [A list of things you should do when moving into your new home and a few regular maintenance items.](#)

Maintenance: • [Scheduled maintenance can avoid repairs and extend the life expectancy of many home components.](#) This document helps you look after your home.

When Things Go Wrong: • [Unpleasant surprises are unfortunately part of homeownership. This document helps to explain why things happen and why your home inspector may not have predicted it.](#)

Standards of Practice: • [This document sets out what a professional home inspection should include, and guides the activities of our inspectors.](#)

END OF REPORT

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

LINKS

PHOTOS

MORE INFO

REFERENCE

The links below connect you to a series of documents that will help you understand your home and how it works. These are in addition to links attached to specific items in the report.

Click on any link to read about that system.

» 01. ROOFING, FLASHINGS AND CHIMNEYS

» 02. EXTERIOR

» 03. STRUCTURE

» 04. ELECTRICAL

» 05. HEATING

» 06. COOLING/HEAT PUMPS

» 07. INSULATION

» 08. PLUMBING

» 09. INTERIOR

» 10. APPLIANCES

» 11. LIFE CYCLES AND COSTS

» 12. SUPPLEMENTARY

Asbestos

Radon

Urea Formaldehyde Foam Insulation (UFFI)

Lead

Carbon Monoxide

Mold

Household Pests

Termites and Carpenter Ants

» 13. HOME SET-UP AND MAINTENANCE

» 14. MORE ABOUT HOME INSPECTIONS